

Image:E1500bridgingerrorafterreset.jpg

Bridging error on the e1200v2 and e1500 (at minimum these two models) cause a lack of ethernet LAN port activity after flashing/resetting.